



---

## EMS报告splog.running.normally消息

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/EMS\\_reports\\_splog.running.normally\\_...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/EMS_reports_splog.running.normally_...)

Updated: Wed, 22 Apr 2026 04:06:13 GMT

### 适用场景

ONTAP 9

### 问题描述

以下消息是EMS日志中的输出。

```
[?] Mon Apr 05 03:11:07 UTC [Node-01: mgmt_port_link_status_poll:
spmgmt.driver.timeout:error]: The software driver for the Service Processor
(SP) detected a problem: Unable to update SP network information at this time.
[?] Mon Apr 05 03:11:07 UTC [Node-01: spsm_listener: sp.update.status:debug]:
params: {'reason': 'sp_startup_notify_servprocd: SP startup handler has been
called. '}
[?] Mon Apr 05 03:11:11 UTC [Node-01: splog_main: splog.running.normally:info]:
Process splogd is operating normally.
[?] Mon Apr 05 03:12:13 UTC [Node-01: rlm_hbtrcv_non_blocking:
```

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
sp.update.status:debug]: params: {'reason': 'sp_bootup_notify_servprocd: SP  
online handler has been called '}  
[?] Mon Apr 05 03:12:47 UTC [Node-01: cf_worker:  
cf.hwassist.notifyCfgSuccess:debug]: params: {'hwtype': 'SP'}
```