



一个节点上缺少FAS500f内部磁盘

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/FAS500f_internal_disk_missing_on_on...

Updated: Wed, 22 Apr 2026 07:31:09 GMT

适用场景

- ONTAP 9
- FAS500f

问题描述

- FAS500f节点的内部磁盘架中缺少一个磁盘。

```
slot 0: Virtual NVMe Host Adapter 0n 1 : NETAPP X4020S173A15TNQF NA54 14651.0GB 4160B/sect  
(XXXXXXXXXXXXXXXX) <<<< Bay 0 is missing 2 : NETAPP X4020S173A15TNQF NA54 14651.0GB 4160B/sect  
(XXXXXXXXXXXXXXXX) 3 : NETAPP X4020S173A15TNQF NA54 14651.0GB 4160B/sect (XXXXXXXXXXXXXXXX)  
4 : NETAPP X4020S173A15TNQF NA54 14651.0GB 4160B/sect (XXXXXXXXXXXXXXXX)
```

- HA组通知(HA组错误：磁盘/磁盘架计数不匹配)错误
- EMS日志显示磁盘缺失：

[NODE-06 : Svc_QUEUE_THREE : cf.disk.inventory.mismatch:debug]:磁盘状态?? 最近更改过或节点(节点-06)缺少磁

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

盘。

- 磁盘重新拔插/更换无法解决此错误。
- 换用已知良好的备用磁盘、但同一磁盘托架出现错误。
- 重新启动节点不能解决此错误。