



sysconfig -a 中缺少夹层卡

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Mezzanine_card_is_missing_in_sysco...

Updated: Wed, 22 Apr 2026 13:15:39 GMT

适用场景

- 夹层卡
- FAS 系统

问题描述

中缺少夹层卡 `sysconfig -a`。

示例：

缺少 `e0e` 和 `e0f`。

```
slot 0: 40G/100G Ethernet Controller CX5
  e0c MAC Address:      d0:39:ea:33:cc:7f (auto-100g_cr4-fd-up)
  QSFP Vendor:         Molex
  QSFP Part Number:    112-00595
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
    QSFP Serial Number: 93A2106820934
e0d MAC Address:      d0:39:ea:33:cc:80 (auto-100g_cr4-fd-up)
    QSFP Vendor:       Molex
    QSFP Part Number:  112-00595
    QSFP Serial Number: 93A2106820988
Device Type:         CX5 PSID(NAP0000000005)
Firmware Version:   16.26.4012
slot 0: 10G/25G Ethernet Controller CX5-Mezz
e0g MAC Address:     d0:39:ea:34:ed:0e (auto-unknown-fd-down)
e0h MAC Address:     d0:39:ea:34:ed:0f (auto-unknown-fd-down)
Device Type:         CX5 PSID(NAP0000000007)
Firmware Version:   16.26.4012
```