



网络端口 e3b 显示为 auto-unknown-fd-down

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Network_port_e3b_is_showing_as_aut...

Updated: Wed, 22 Apr 2026 11:57:58 GMT

适用于

- C800
- 双 10G/25G 以太网控制器 CX5

问题描述

e3b端口已关闭

- 插槽3：双10G/25G以太网控制器CX5
- 状态：auto-unknown-fd-down
- SFP供应商：Finisar corp.
- SFP PN：FTLF8536P5BCL

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information