



由于SP HBT丢失、节点崩溃

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Node_panic_due_to_SP_HBT_MISSED

Updated: Wed, 22 Apr 2026 04:09:18 GMT

适用场景

- BMC 15.10
- AF-A250

问题描述

- 之后出现节点崩溃 SP HBT MISS。
- 当前BMC固件为15.10、已修复错误 [139656](#) 和错误 [144866](#)