



由于PDU问题描述、节点(检测到低端PSU1)错误

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Node__\(Low-Line_PSU1_detected\)_E...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Node__(Low-Line_PSU1_detected)_E...)

Updated: Wed, 22 Apr 2026 07:32:35 GMT

适用场景

- ONTAP 9
- AFF-A30

问题描述

EMS-log-file.GZ

[?] Weed A APR 16 : 49 : 21 -0500 [Node : ENV_Mgr : callhome.chassis.ps.degraded:error]: Call home for Low-Line PSU1 Detected

[?] Fri Ar 18 16 : 50 : 19 -0500 [Node : ENV_Mgr : callhome.chassis.ps.degraded:error]: Call home for Low-Line PSU1 Detected

[?] 19年4月周六16 : 50 : 50 -0500 [Node : ENV_Mgr : callhome.chassis.ps.degraded:error]: Call home for Low-Line PSU1 Detected