



# CXone Mpower EXPERT

## 崩溃：A700s上的DIMM 7ECC错误

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/PANIC\\_\\_ECC\\_error\\_at\\_DIMM\\_7on\\_A...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/PANIC__ECC_error_at_DIMM_7on_A...)

Updated: Wed, 22 Apr 2026 11:58:01 GMT

### 适用场景

AFF A700

### 问题描述

控制器重新启动并显示以下消息：

```
PANIC: ECC error at DIMM 7: 2C-25-1902-F013FB17, ADDR 0x5be139bc80, (Node(0),
Memory controller(1), CH(2), DIMM(1), Rank(0), Bank Group(0), Bank(0x2),
Row(0x16b17), Col(0x178)) Uncorrectable Machine Check Error at CPU1. BDWL_HA1
Error:
STATUS<0xfe00004000010090> (Val, OverF, UnCor, Enable, MiscV, AddrV, PCC, CorrSts(0), CorrCnt(0),
0,
Read) ErrCode(0x90) MISC<0x0000000022281c86> (HaDbBank(0), PE(0), ReqOpcode(0x1), RNID(0x1)
BDWL_iMC4 Error:
DQ(45) Burst(0), DQ(46) Burst(0), DQ(47) Burst(0), DQ(44) Burst(1), DQ(46) Burst(2), DQ(47) Burst
```

0,

Read) ErrCode (0x90) MISC<0xd2213e7b1b079600> (SECDIMM (0x2) , FSTDIMM (0x2) , SECRANK (0x4) , FST

9.8P14: Tue Aug 23 11:33:04 EDT 2022