



CXone Mpower EXPERT

端口无法与 LACP 聚合同步

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Port_cannot_synchronize_with_the_LA...

Updated: Wed, 22 Apr 2026 07:30:09 GMT

适用场景

- ONTAP 9
- FAS / AFF 系统

问题描述

- `ifgrp` 已部分关闭
- `EMS.log` 报告错误：`intr: pvif.lacp.outofsync:alert]: ifgrp a0c, port e0d cannot synchronize with the LACP aggregate`
- `network port ifgrp show` 命令并不会显示所有成员端口、`active ports` 即使所有成员端口均处于已启动状态。