



串行端口无响应

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Serial_port_is_not_responding

Updated: Wed, 22 Apr 2026 04:07:44 GMT

适用场景

FAS2700

问题描述

- 串行端口无响应
- 同一串行电缆适用于配对节点