



SPLinkDownAlert经常出现

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/SPLinkDownAlert_occurs_frequently

Updated: Wed, 22 Apr 2026 06:53:26 GMT

适用场景

- AS2552
- FAS2554
- AFF8040
- AFF A300
- ONTAP 9
- 服务处理器 (SP)
- 底板管理控制器 (BMC)

问题描述

SPLinkDownAlert经常出现

```
9/8/2023 05:58:34 node-01 NOTICE hm.alert.cleared: Alert Id =  
SPLinkDownAlert , Alerting Resource = SP Config cleared by monitor controlle  
9/8/2023 06:00:35 node-02 NOTICE hm.alert.cleared: Alert Id =
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
SPLinkDownAlert , Alerting Resource = SP Config cleared by monitor controller
9/8/2023 06:18:34 node-01 ALERT hm.alert.raised: Alert Id =
SPLinkDownAlert , Alerting Resource = SP Config raised by monitor controller
9/8/2023 06:20:35 node-02 ALERT hm.alert.raised: Alert Id =
SPLinkDownAlert , Alerting Resource = SP Config raised by monitor controller
```