



SP HBT在EMS日志中丢失

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/SP_HBT_MISSED_in_EMS_log

Updated: Wed, 22 Apr 2026 07:13:34 GMT

适用于

- Data ONTAP 8
- ONTAP 9
- 服务处理器 (SP)

问题

系统SP在EMS中出现类似的"EMS HBT遗漏"错误：

```
Mon Oct 25 13:10:39 +0900 [Nodename: spsm_listener:  
callhome.sp.hbt.missed:notice]: Call home for SP HBT MISSED
```

```
Tue Jun 21 10:32:10 +0900 [Nodename: spsm_listener:  
sp.heartbeat.stopped:error]: Have not received a IPMI heartbeat from the  
Service Processor (SP) in last 20 seconds.
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

