



TIC温度值与BMC和ONTAP不同

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/TIC_Temp_values_different_from_BM...

Updated: Wed, 22 Apr 2026 07:28:57 GMT

适用场景

- ONTAP 9
- AFF A250
- 温度指示器控制器(Tic)

问题描述

- ONTAP和BMC之间的TIC温度值不匹配
- 位于Node PLATFORMA-sensors.XML上

```
PLATFORM-SENSORS.XML:Sensor Name: TIC Temp
```

```
Last Sensor Value: 89
```

```
SP-LATEST-IPMI:
```

```
===== sensor =====  
Sensor name | reading | unit | status| lnr | lcr | lnc | unc | ucr | unr  
TIC_TEMP | 76.000 | degrees C | ok | 1.000 | 3.000 | 5.000 | 101.000 | 103.000 |  
105.000
```