



无法登录到SP / BMC

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Unable_to_login_to_SP__BMC

Updated: Wed, 22 Apr 2026 07:27:56 GMT

适用场景

- AFF C190A
- FAS 8200
- FAS9000/AFF700
- FAS 27xx

问题描述

- 无法BMC通过SP登录到SSB/SSH (底板管理控制器)。
- 报告"Login Timed Out" Messages Unable to login to SP。

```
::>  
Switching console to Service Processor  
Service Processor Login:  
Password:  
Login timed out after 60 seconds
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

::>