



# CXone Mpower EXPERT

## "sysconfig -M"输出中出现异常字符

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Unusual\\_characters\\_appear\\_in\\_sysco...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Unusual_characters_appear_in_sysco...)

Updated: Wed, 22 Apr 2026 04:07:55 GMT

### 适用场景

- AFF 和FAS 型号
- 32 GB DDR4 DIMM
- ONTAP 9.9.1

### 问题描述

- 命令 `sysconfig -M` 输出显示"?" 具有DIMM供应商部件号(X4B32QB4BNTDSO-B-NT1)。

示例：

```
::*>run -node node-01 sysconfig -M
!Mother Board!952126003456!!111-04198!F0!
!Chassis!042126033471!!111-04200!B0!
!DIMM-2!CE-03-2110-190CF85E!!X4B32QB4BNTDSO-B-NT1?!!
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
!DIMM-4!CE-03-2110-190CE2A6!!X4B32QB4BNTDSO-B-NT1?!!
!NVDIMM-11!2C-0F-2113-2DF26C6E!!18ASF2G72XF13G2WP1AB,!!
!DIMM-13!CE-03-2110-190C9813!!X4B32QB4BNTDSO-B-NT1?!!
!DIMM-15!CE-03-2110-190CD3CF!!X4B32QB4BNTDSO-B-NT1?!!
```

- 命令 `system controller fru show-manufacturing-info` 输出显示相同的问题描述。

示例：

```
::*>system controller fru show-manufacturing-info -node node-01
```

FRU Description	FRU Serial Number	FRU Part Number	FRU Rev.
DIMM-2	CE-03-2110-190C5C5E	X4B32QB4BNTDSO-B-NT1?	
	-		
DIMM-4	CE-03-2110-190C5B69	X4B32QB4BNTDSO-B-NT1?	
	-		
NVDIMM-11	2C-0F-2108-2E85CF5B	18ASF2G72XF13G2WP1AB,	
	-		
DIMM-13	CE-03-2110-190C6289	X4B32QB4BNTDSO-B-NT1?	
	-		
DIMM-15	CE-03-2110-190C6284	X4B32QB4BNTDSO-B-NT1?	

注意：部件号的最后一个数字可能会有所不同(1、2、3、4等)。例如：X4B32QB4BNTDSO-C-NT3?