



# CXone Mpower EXPERT

---

## system controller service-event show 命令返回警告：无法列出节点上的条目

[https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/warning\\_reported\\_when\\_executing\\_sy...](https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/warning_reported_when_executing_sy...)

Updated: Wed, 22 Apr 2026 11:39:22 GMT

### 适用场景

- ONTAP 9
- 服务处理器(SP)

### 问题描述

执行 `system controller service-event show` 命令时、会出现以下错误。

```
cluster::> system controller service-event show
Warning: Unable to list entries on node node01. Timeout: Operation
        "spcc_hsam_sp_read_fru_faults_iterator::modify_imp()" took longer than
        25 seconds to complete
        Unable to list entries on node node02. Timeout: Operation
        "service_event_iterator::next_imp()" took longer than 25 seconds to
```

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
complete
Error: show failed: Timeout: Operation "service_event_iterator::next_imp()"
took longer than 25 seconds to complete
```