



为什么从 ONTAP 9.15.1 中删除了“shelf.esh4.auto.reset.enable”？

https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-KBs/Why_%22shelf.esh4.auto.reset.enable...

Updated: Wed, 22 Apr 2026 13:25:32 GMT

适用场景

ONTAP 9

问题解答

- “shelf.esh4.auto.reset.enable”表示ESH4搁架自动重置以恢复硬件问题。
- 由于ESH4搁架不再受支持，shelf.esh4.auto.reset.enable选项被删除。

追加信息

其他信息文本

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information