



---

## AutoSupport 消息：检测到不一致的路由规则

[https://kb-cn-stage.netapp.com/on-prem/SolidFire/Element\\_OS\\_Kbs/AutoSupport\\_Message\\_Inconsist...](https://kb-cn-stage.netapp.com/on-prem/SolidFire/Element_OS_Kbs/AutoSupport_Message_Inconsist...)

Updated: Wed, 22 Apr 2026 07:30:02 GMT

### 适用场景

NetApp Element 软件

### 问题描述

- **ASUP** : SolidFire Alert from <cluster name> (Network Warning) Inconsistent routing rules detected
- **NetApp SolidFire Active IQ** : Inconsistent routing rules detected. Routing rule to nodeID mapping: <routing mismatch information>