



Element 集群报告 failedSpacedToFull 和 sensorReadingFaed 警报

https://kb-cn-stage.netapp.com/on-prem/SolidFire/Element_OS_Kbs/Element_cluster_reports_failedSp...

Updated: Wed, 22 Apr 2026 05:25:52 GMT

适用场景

NetApp Element 软件

问题描述

- 一个存储节点报告如下 failedSpaceTooFull 警报(值X可能是超过24%的任何值)，并且未被清除。

```
failedSpaceTooFull - Slice Service is using X% of the space reserved for failed writes. Call SolidFire Support to resolve this issue.
```

- 另一个存储节点 sensorReadingFailed 警报为bleow：

```
sensorReadingFailed - IPMI diagnostics are currently unresponsive. Please contact support if this problem persists.
```

```
sensorReadingFailed - BMC Self Test failed. This may impact IPMI based services and a BIOS/BMC update may be recommended.
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

- ESXi节点似乎具有问题描述访问存储的权限。某些VM无响应。