



Element 软件升级期间出现 FailedSpaceTooFull 错误警报

https://kb-cn-stage.netapp.com/on-prem/SolidFire/Element_OS_Kbs/failedSpaceTooFull_error_alert_d...

Updated: Wed, 22 Apr 2026 07:29:02 GMT

适用场景

- NetApp SolidFire 存储节点
- NetApp H系列存储节点
- NetApp Element软件12.3及更高版本

问题描述

- 在Element软件升级期间或在更换NetApp存储节点期间自动执行RTFI期间、NetApp SolidFire Active IQ上某些节点会显示以下错误。

Error Code `failedSpaceTooFull`

详细信息: `Slice service is using 25% of the space reserved for failed writes. Call SolidFire Support to resolve this issue.`

- 此错误将在节点完成后不久得到解决 升级

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

