



---

## 更改IP后、H610S BMC WebUI无法访问

[https://kb-cn-stage.netapp.com/on-prem/SolidFire/hardware\\_Kbs/H610S\\_BMC\\_WebUI\\_can't\\_access\\_...](https://kb-cn-stage.netapp.com/on-prem/SolidFire/hardware_Kbs/H610S_BMC_WebUI_can't_access_...)

Updated: Wed, 22 Apr 2026 04:09:18 GMT

### 适用场景

NetApp H610S

### 问题描述

将BMC IP地址更改为其他网络后、无法访问此BMC。