



IPMI诊断程序当前无响应警告从H610s持续存在

https://kb-cn-stage.netapp.com/on-prem/SolidFire/hardware_Kbs/IPMI_diagnostics_are_currently_unre...

Updated: Wed, 22 Apr 2026 07:33:18 GMT

适用场景

- NetApp H610s节点
- NetApp Element软件12.0至12.3.2

问题描述

`sensorReadingFailed` 即使在尝试了所有已知解决方法后、H610s节点仍会显示消息。

- `sensorReadingFailed: IPMI diagnostics are currently unresponsive. Please contact support if this problem persists.`
- `sensorReadingFailed: BMC Self Test failed. This may impact IPMI based services and a BIOS/BMC update may be recommended`
- `BMC Self Test failed. Postponing Fault. mBmcSelfTestFailureCount=1 cNumFailedSelfTestsForFault=1`