



错误"LIF报告了tcp.conn.inconsistent"

https://kb-cn-stage.netapp.com/on-prem/ontap/da/NAS/NAS-KBs/Error_tcp.conn.inconsistent_reported...

Updated: Wed, 22 Apr 2026 04:07:10 GMT

适用场景

ONTAP 9.8P11、9.9.1P6、9.10.1及更高版本

问题描述

EMS日志中报告tcp.conn.inconsistent错误事件：

```
[node1: kernel: tcp.conn.inconsistent:error]: Inconsistency between TCP metadata and the socket send buffer occurred for the connection with local address "10.100.200.x:445" and remote address "10.110.200.x:45704". The inconsistency occurred while processing "[cc_cong_signal:506]". The connection is "NOT Reset".
```