



AFF 8060 集群ping失败

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/AFF_8060_cluster_ping_fail

Updated: Wed, 22 Apr 2026 11:39:41 GMT

适用场景

- ONTAP 9
- AFF8060

问题描述

- `::*>cluster ping-cluster` 在4个CN1610有交换机集群上、命令失败。

示例：

```
::*> cluster ping-cluster -node node01
Host is node01
Getting addresses from network interface table...
Cluster node01_clus1 xx.xx.xx.xx node01 e0a
Cluster node01_clus2 xx.xx.xx.xx node01 e0d
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
Cluster node02_clus1 xx.xx.xx.xx node02 e0a
Cluster node02_clus2 xx.xx.xx.xx node02 e0d
Ping status:
....
Basic connectivity succeeds on 2 path(s)
Basic connectivity fails on 2 path(s)
```

- 集群ping结果显示、四个集群CN1610交换机无法相互通信。
- 未找到硬件问题描述。