



AutoSupport消息：Multiple Fan failed.

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/AutoSupport_message__Multiple_F...

Updated: Wed, 22 Apr 2026 03:53:50 GMT

适用场景

Data ONTAP 7及更早版本

问题描述

MFANFL:HA Group Notification from FilerX (MULTIPLE FAN FAILURE) CRITICAL

Mon Jun 18 09:00:05 CEST [monitor.fan.critical:EMERGENCY]: 2 fans have failed. Replace them to avoid overheating. If not corrected, system will shutdown in 2 minutes.

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information