



CXone Mpower EXPERT

集群交换机升级期间出现崩溃

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/CLAM_Panic_during_cluster_switch...

Updated: Wed, 22 Apr 2026 07:33:26 GMT

适用场景

- ONTAP 9
- 所有集群互连交换机

问题描述

在集群交换机升级期间、集群中两个节点之一发生崩溃、并显示以下崩溃字符串：

```
PANIC: Received PANIC packet from partner, receiving message is (Coredump and takeover initiated because Connectivity, Liveliness and Availability Monitor (CLAM) has determined this node is out of quorum.) in SK process mlx4_intr_handler on release 9.1P5 (C) on Wed Jul 15 11:07:26 MDT 2020 version: 9.1P5: Sat Jun 10 15:08:23 PDT 2017
```