



---

## 对等集群之间的OKM密钥不匹配

[https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap\\_OS/OS-KBs/OKM\\_keys\\_mismatch\\_between\\_pe...](https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/OKM_keys_mismatch_between_pe...)

Updated: Wed, 22 Apr 2026 08:49:42 GMT

### 适用场景

- MCC
- ONTAP 9
- 板载密钥管理器
- 将SVM-DR迁移到MCC

### 问题描述

运行MetroCluster检查时、板载key-manager显示以下错误、以防止切回：

```
mcc01::*> metrocluster check cluster show -check onboard-key-management -instance
Type of Check: onboard-key-management
Cluster Name: mcc01
Result of the Check: warning
Additional Information/Recovery Steps: Internal Error. Onboard Key Manager hierarchy
```

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

key mismatch between peer clusters. The local and partner clusters do no

Type of Check: onboard-key-management

Cluster Name: mcc02

Result of the Check: warning

Additional Information/Recovery Steps: Internal Error. Onboard Key Manager hierarchy key mismatch between peer clusters. The local and partner clusters do no2 entries were displayed.

Error remain even after following: Some VServers show their status as replication-paused: