



CXone Mpower EXPERT

报告了E系列主机多路径驱动程序配置错误

https://kb-cn-stage.netapp.com/on-prem/E-series/SANtricity-OS-Kbs/E-Series_Host_multipath_driver_c...

Updated: Wed, 22 Apr 2026 07:30:14 GMT

适用场景

- NetApp E 系列
- NetApp SANtricity操作系统

问题描述

`Host multipath driver configuration error detected` 严重事件会在主要事件日志中进行报告。系统处于“需要引起注意”状态，Recovery Guru显示的警报 `Incorrect Host Multipath Driver`。