



接管尝试被密钥管理器否决

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/Takeover_attempt_was_vetoed_by...

Updated: Wed, 22 Apr 2026 08:24:17 GMT

适用场景

- ONTAP 9
- FAS

问题描述

- 接管操作已中止、并出现以下错误：

```
::> storage failover show
```

Node	Partner	Takeover Possible	State Description
node-01	node30n	true	Connected to node-02. Previous takeover attempt by node-02 was

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

00000000000000000200000000000100d7b8fef5668a7e7383876f323eab6bf0000000000000000

Node: Node-02

Key Manager: 10.216.XX.XXX

Server Status: Available

Key Tag	Key Type	Restored
fas2520-rtp-2a	NSE-AK	yes
Key ID: 00000000000000000200000000000100983cd5df1ff4663fa85d3bfb9ecbc699000000000000000		
fas2520-rtp-2a	NSE-AK	yes
Key ID: 00000000000000000200000000000100ca6d2fea44c952726e602e1741625770000000000000000		
fas2520-rtp-2a	NSE-AK	yes
Key ID: 00000000000000000200000000000100d7b8fef5668a7e7383876f323eab6bf0000000000000000		

6 entries were displayed.