



BES 53248不支持以太网交换机警报

https://kb-cn-stage.netapp.com/on-prem/ontap/Ontap_OS/OS-KBs/Unsupported_Ethernet_switch_alert...

Updated: Wed, 22 Apr 2026 11:40:12 GMT

适用场景

- ONTAP 9
- BES 53248集群网络交换机

问题描述

- `system health alert show` 报告 `Unsupported Ethernet switch is detected`。

```
Node: NodeA
Resource: Swtich01
Severity: Major
Indication Time: Mon Jan 16 17:00:52 2023
Suppress: false
Acknowledge: false
Probable Cause: Unsupported Ethernet switch is detected.
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

Possible Effect: Communication problems and network connectivity issues occur.

Corrective Actions: Unsupported Ethernet switch "Swtich01" found. Connect a supported Ethernet switch to the network.

- `system switch ethernet show` 返回 Unsupport Model 其中一个交换机的完整输出和报告需要很长时间

```
Cluster::~*> system cluster-switch show
```

Switch	Type	Address	Model
Swtich01	cluster-network	192.168.x.x	OTHER

Serial Number: Unknown
Is Monitored: false
Reason: **Unsupported Model**
Software Version: BES-53248A1, 3.4.4.6, Linux 4.4.211-28a6fe76, 2016.05.00.05
Version Source: SNMP