



BES-53248 集群交换机意外重新启动

https://kb-cn-stage.netapp.com/on-prem/Switches/Broadcom-KBs/BES-53248_cluster_switch_unexpect...

Updated: Wed, 22 Apr 2026 07:31:48 GMT

适用场景

- ONTAP 9
- BES-53248

问题描述

- BES-53248 集群交换机意外关闭、由于端口关闭、导致集群的生命周期发生迁移：

```
[cluster1-01: vifmgr: vifmgr.clus.linkdown:EMERGENCY]: The cluster port e3a on node cluster1-01 has gone down unexpectedly.
```

```
[cluster1-01: vifmgr: vifmgr.reach.noreach:notice]: Network port e3a on node cluster1-01 cannot reach its expected broadcast domain Cluster:Cluster. No other broadcast domains appear to be reachable from this port.
```

```
[cluster1-01: vifmgr: vifmgr.reach.skipped:notice]: Network port e3a on node cluster1-01 was not scanned for reachability because it was administratively or operationally down at the time of the scan.
```

```
[cluster1-01: vifmgr: vifmgr.lifmoved.linkdown:notice]: LIF cluster1-01_clus1 (on
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

virtual server 4294967293), IP address 169.254.12.54, is being moved to node cluster1-01, port e3b.

- 这些端口在以下时间后不久恢复正常：

```
[cluster1-01: kernel: netif.linkUp:info]: Ethernet e3a: Link up.
```

```
[cluster1-01: vifmgr: vifmgr.portup:notice]: A link up event was received on node cluster1-01, port e3a.
```

交换机日志中没有明确的重新启动原因、例如内核崩溃、风扇故障或温度问题。