



复制脚本时， BES-53248 RCF 配置验证失败

https://kb-cn-stage.netapp.com/on-prem/Switches/Broadcom-KBs/BES-53248_RCF_configuration_vali...

Updated: Wed, 22 Apr 2026 08:34:07 GMT

适用场景

BES-53248 集群交换机

问题描述

BES 53248 集群交换机在尝试复制 RCF 脚本时报告验证错误：

```
(Switch)#copy http://172.19.2.1/RCF-Cluster-HA.txt nvram:script RCF-Cluster-  
HA.scr
```

```
Management access will be blocked for the duration of the transfer
```

```
Are you sure you want to start? (y/n) y
```

```
HTTP Configuration Script transfer starting...
```

```
Validating configuration script...
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

Configuration script validation failed.

Following lines in the script may have problem:

Line 41:: passwords lock-out 0

Line 55:: police-simple rate-percent 60 64 conform-action transmit violate-action transmit

Line 59:: police-simple rate-percent 60 64 conform-action transmit violate-action transmit

Line 68:: police-simple rate-percent 60 64 conform-action transmit violate-action transmit

Line 72:: police-simple rate-percent 60 64 conform-action transmit violate-action transmit

Total error Lines :: 5

The file being downloaded has potential problems.

Do you want to save this file? (y/n)