



BES 53248许可证密钥文件传输失败

https://kb-cn-stage.netapp.com/on-prem/Switches/Broadcom-KBs/BES_53248_License_key_file_transf...

Updated: Wed, 22 Apr 2026 07:30:07 GMT

适用场景

- BES-53248
- 应用额外许可证

问题描述

- 尝试对其他端口应用许可证文件时遇到以下错误。

```
(sw1)#copy http://10.10.10.10/licensefile.dat nvram:license-key 1
```

```
Mode..... HTTP
Set Server IP..... 10.10.10.10
Path..... ./
Filename..... licensefile.dat
Data Type..... license
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
Management access will be blocked for the duration of the transfer
Are you sure you want to start? (y/n) y
HTTP License Key transfer starting...
```

```
License key file transfer failed
```

- 已尝试使用HTTP、FTP、SFTP、并显示相同的错误消息。
- 已确认可通过这些协议从备用主机访问此文件。
- 已确认正在使用正确的文件名、并且符合知识库文章：[BES-53248上的许可证安装失败、许可证密钥文件传输失败](#)中所述的标准
- 已确认正在使用正确的许可证文件(许可证与序列号相关联)。