



BES-53248上的集群网络降级

https://kb-cn-stage.netapp.com/on-prem/Switches/Broadcom-KBs/CLUSTER_NETWORK_DEGRADE...

Updated: Wed, 22 Apr 2026 07:35:13 GMT

适用场景

- AF/FAS系统
- BES-53248

问题描述

- EMS事件ID `callhome.clus.net.degraded`
- 在集群端口上发现持续的数据包丢失。

```
[vifmgr: vifmgr.cluscheck.ctdpktloss:alert]: Continued packet loss when pinging
from cluster lif node_name01_clus2 (node node_name) to cluster lif
node_name-01_clus1 (node node_name-01).
```

```
[vifmgr: vifmgr.cluscheck.ctdpktloss:alert]: Continued packet loss when pinging
from cluster lif node_name01_clus1 (node node_name) to cluster lif
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
node_name-03_clus2 (node node_name-03).  
[vifmgr: vifmgr.cluscheck.ctdpktloss:alert]: Continued packet loss when pinging  
from cluster lif node_name01_clus1 (node node_name) to cluster lif  
node_name-02_clus2 (node node_name-02).  
[vifmgr: vifmgr.cluscheck.ctdpktloss:alert]: Continued packet loss when pinging  
from cluster lif node_name01_clus1 (node node_name) to cluster lif  
node_name-01_clus2 (node node_name-01).
```