



CXone Mpower EXPERT

启动时出现Brocade FC错误、无法挂载Ext2

https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/Brocade_FC_error_on_boot_failed_to...

Updated: Wed, 22 Apr 2026 07:30:39 GMT

适用场景

- Brocade G610
- Brocade G620
- Brocade G630
- 光纤操作系统8.2.2版

问题描述

- Brocade光纤交换机无法启动到光纤操作系统
- [使用串行控制台电缆进行连接](#)，并关闭并重新启动交换机错误消息
- 更新SSH证书后、交换机无法启动

示例：

```
Failed to mount Ext2 filesystem
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

```
hda: task_in_intr: error=0x44 { DriveStatusError UncorrectableError },  
LBAsect=473188, sector=473188
```

A fatal CF card failure has been detected. The system will be rebooted. Please contact your service provider for CF card replacement.

BUS error, core dumped