



Brocade G630交换机意外重新启动

https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/Brocade_G630_switch_reboots_unexp...

Updated: Wed, 22 Apr 2026 07:31:09 GMT

适用场景

Brocade FOS 9.0.1c版

问题描述

运行9.0.1c的Brocade G630交换机意外重新启动、而未生成任何核心转储。

2022/05/30-14:08:07, [HAM-1004], 1656, CHASSIS, INFO, BrocadeG630, Processor rebooted - Reset.

2022/06/04-04:03:05, [HAM-1004], 2083, CHASSIS, INFO, BrocadeG630, Processor rebooted - Reset.

2022/06/04-10:07:55, [HAM-1004], 2098, CHASSIS, INFO, BrocadeG630, Processor rebooted - Reset.

2022/06/05-07:22:41, [LOG-1004], 3739, FID 128, INFO, IGBD012102, Log message AN-1014 flooding detected and blocked.

2022/06/05-07:58:17, [HAM-1004], 3740, CHASSIS, INFO, BrocadeG630, Processor

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

rebooted - Reset.