



CXone Mpower EXPERT

Brocade交换机报告错误：组根具有无效属性

https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/Brocade_switch_reports_Error_Group...

Updated: Wed, 22 Apr 2026 08:33:53 GMT

适用场景

- Brocade交换机
- FOS v9.1.1a

问题描述

- 升级到FOS 9.1.0后、每5分钟会记录一次SEC-3089消息
- errdump 日志显示：

```
2023/02/03-10:14:52 (UTC), [SEC-3089], 40, FID 128, ERROR, Switchxx, Detected  
incorrect configuration in user database. Error: Group root has invalid  
attributes
```