



Brocade : 固件下载失败

https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/Brocade__Firmware_download_failed

Updated: Wed, 22 Apr 2026 07:31:34 GMT

适用场景

- Brocade 交换机
- 固件升级
- 光纤 MetroCluster

问题描述

Brocade交换机固件升级失败：

```
Firmware is being downloaded to the switch. This step may take up to 30 minutes.  
Could not open /tmp/fwdl_new_rel.txt for reading.  
Preparing for firmwaredownload...  
Server IP: 1.2.3.4, Protocol IPv4  
Reached EOF of TAR file looking for release.plist  
Firmware download failed - Unable to access the package list file. Check whether the
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

file name is specified properly. (0x12)