



---

## CVE-2020-10188是否会影响Brocade交换机？

[https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/If\\_CVE\\_2020\\_10188\\_affect\\_Brocade\\_...](https://kb-cn-stage.netapp.com/on-prem/Switches/Brocade-KBs/If_CVE_2020_10188_affect_Brocade_...)

Updated: Wed, 22 Apr 2026 11:39:17 GMT

### 适用场景

Brocade 交换机上的端口

### 问题解答

- 所有早于v9.9.0a的Brocade Fabric OS版本以及介于v9.0.1到v9.0.1D的Brocade Fabric OS版本
- Brocade Fabric OS中提供的安全更新：v9.1.0、v9.0.1e、v9.0.0a、v8.1.2k、v8.2.1e、v8.2.0\_CBN3、v8.2.2c、v7.4.2h
- 目前已知Broadcom产品中的任何其他Brocade光纤通道产品均不受此漏洞的影响。
- 禁止使用telnet是一种有效的临时解决策。

### 追加信息

请参见 [本文所载的资料](#)

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information