



---

## 在 CN1610 交换机上升级固件后出现集群互连连接问题

[https://kb-cn-stage.netapp.com/on-prem/Switches/NetApp-KBs/Cluster\\_interconnect\\_connectivity\\_issu...](https://kb-cn-stage.netapp.com/on-prem/Switches/NetApp-KBs/Cluster_interconnect_connectivity_issu...)

Updated: Wed, 22 Apr 2026 08:25:09 GMT

### 适用于

- CN1610 网络交换机
- FastPath 1.3.0.3

### 问题

- 系统报告节点的集群网络端口之间的连接问题。
- 可以在集群的节点上观察到类似此类消息：

```
node1: Total Packet Loss - Ping failures detected between node1_clus1
(xxx.xxx.xxx.xxx ) on node1 and node2_clus2 ( xxx.xxx.xxx.xxx ) on node2
node2: Total Packet Loss - Ping failures detected between node2_clus1 (
xxx.xxx.xxx.xxx ) on node2 and node1_clus2 ( xxx.xxx.xxx.xxx) on node1
```