



CONTAPEXT-144 : ATTO FibreBridge 7500N 和 7600N 可能意外重新启动

<https://kb-cn-stage.netapp.com/on-prem/ontap/MC/MC-Issues/CONTAPEXT-144>

Updated: Wed, 22 Apr 2026 08:24:15 GMT

问题描述

ATTO Bridge 因不可纠正的内存错误重启。

单比特错误：

037784 05:30:33 03/29/17 CRIT ECC 检测到不可纠正的单比特错误。D:1 S:0e6d6607

037787 05:30:33 03/29/17 CRIT 检测到软件中断异常 (SWI) (025D)

037794 00:00:02 01/01/00 INFO 重置。HW 代码：软件热重启

037795 00:00:02 01/01/00 INFO 重置。原因：检测到严重硬件错误

多比特错误：

0070B5 07:38:21 06/15/20 CRIT ECC 检测到多比特错误。地址：03761bc0 STS:09

0070C7 07:38:21 06/15/20 INFO 0030a0c8<-003f1b10 | SP[00a220c0] FP[00a220c0]

0070C8 07:38:21 06/15/20 INFO 发生异常。可能存在冗余的前置日志条目

0070C9 00:00:05 01/01/00 INFO 重置。HW 代码：软件热重启

0070CA 00:00:05 01/01/00 INFO 重置。原因：检测到严重硬件错误

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information