



## CONTAPEXT-705 : ATto 光纤桥 7600N 可能会意外重新启动

<https://kb-cn-stage.netapp.com/on-prem/ontap/MC/MC-Issues/CONTAPEXT-705>

Updated: Wed, 22 Apr 2026 08:25:35 GMT

### 问题描述

- ATto 网桥重新启动通知调用主目录由节点触发：  
HA Group Notification from NODE1 (Bridge Unexpected Reboot: FB7600NXXXXXX) ALERT
- 来自 ATTO Bridge 事件日志：CRIT ECC Multi-bit error detected. D:2 S:00000f47 A:4a715dc0  
INFO Reset. HW Code: Software Warm  
CRIT Software Interrupt Exception Detected (SWI) (007A)  
INFO Reset. Reason: Critical Hardware Error Detected  
或者  
CRIT ECC 检测到单位错误。D:1 S:00000083 A:44ff9000  
信息重置。硬件代码：L4 看门狗 0 预热  
信息重置。原因：未处理的硬件看门狗中断  
信息启动/重置发生 (001P)