



---

## CONTAPEXT-986(1995) : AT托7500/7500N/7600网桥重新启动，硬件代码软件为Warm

<https://kb-cn-stage.netapp.com/on-prem/ontap/MC/MC-Issues/CONTAPEXT-986>

Updated: Wed, 22 Apr 2026 08:25:33 GMT

### 问题描述

- ATTO FibreBridge is rebooting unexpectedly
- dsbridge\_log\_FB7500NXXXXXX:
  - INFO Exception occurred. Possible redundant preceding log entries
  - INFO Reset. HW Code: Software Warm
  - INFO Reset. Reason: Critical Hardware Error Detected
  - SYS System date has changed. Current date:[XX/XX/XXXX]
  - INFO Boot/reset occurred (001C)