



CFBMC-3955 : 升级BMC固件后出现温度过低警告

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CFBMC-3955>

Updated: Wed, 22 Apr 2026 07:29:00 GMT

问题描述

在将BMC固件升级到11.10或11.7之后、两个节点都会报告控制器机箱(内部磁盘架)偶尔出现的温度不足警告警报。

示例：

```
[node1: dsa_worker4: ses.status.temperatureWarning:alert]: DS212-12 (S/N
SHJGD23189XXXXX) shelf 0 on channel 0a temperature warning for Temperature sensor
11: non-critical status; undertemperature warning. Current temperature: 0 C (32 F).
This module is on the rear of the shelf at the top left, on shelf module A.
[node1: dsa_worker4: ses.status.temperatureInfo:info]: DS212-12 (S/N
SHJGD23189XXXXX) shelf 0 on channel 0a temperature information for Temperature
sensor 11: normal status.
```