



CFBMC-6107 : BMC 启动后控制器注意 LED 点亮

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CFBMC-6107>

Updated: Wed, 22 Apr 2026 04:07:57 GMT

问题描述

- 控制器注意（琥珀色）LED 亮起，因为 "Bat_Design_Cap" 或 "Bat_Full_Cap" 传感器报告"警告高"或非关键（UNC）上限阈值。
- 从 BMC 输出的服务事件示例：

```
tag   origin   fld                               fault reason
-----
1    bmc     /chassis-1/controller-a/nvbatt-1 Bat_Design_Cap: Current Sensor 95 UNC
```

- BMC 的传感器输出示例：

```
Bat Design Cap warnhigh 12565 W*hr  -- 9100 W*hr 10465 W*hr  --
```

- 受影响的型号：AFF A1K、AFF A90、AFF A70、AFF C80、ASA A1K、ASA A90、ASA A70、FAS90、FAS70