



CFBMC-6191 : AFF A900 、ASA A900 、FAS9500 : BMC意外重新启动

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CFBMC-6191>

Updated: Wed, 22 Apr 2026 07:31:13 GMT

问题描述

- ICMP ping BMC IP地址失败
- BMC无响应并重新启动、并发生以下观察到的事件
- EMS :
[sp.heartbeat.stopped:error]: Have not received a IPMI heartbeat from the Service Processor (SP) in last 600 seconds.
[sp.heartbeat.resumed:info]: Received IPMI heartbeat from the Service Processor (SP).
- SP最新系统事件日志 :
[BMC.critical]: SFPGA: Loaded Primary image
[BMC.notice]: eMMC SLC: 0% - 10% device life time used
[BMC.notice]: eMMC MLC: 0% - 10% device life time used
[BMC.notice]: eMMC Pre EOL: Normal
[BMC.notice]: Running primary version XX