



CFBMC-6985 : AFF A90 SP HBT 丢失并在 10 分钟内因 sp.ipmi.lost.shutdown 而停止

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CFBMC-6985>

Updated: Wed, 22 Apr 2026 07:28:47 GMT

问题描述

- 节点意外关闭，BMC 状态不确定。示例：

```
LOADER-B> bmc status
Firmware Version:   UnknownIPv4 Settings
Failed to get IPv4/IPv6 addressing enables: Unknown IPMI completion code.
Failed to get DHCP setting: Unknown IPMI completion code.
  MAC Address:      N/A - Error
  Using DHCP:       Failed to get DHCP setting: Unknown IPMI completion code.
N/A - Error
  IP Address:       Failed to get address: Unknown IPMI completion code.
N/A - Error
  Gateway:         Failed to get gateway: Unknown IPMI completion code.
N/A - Error
  Netmask:         Failed to get netmask: Unknown IPMI completion code.
N/A - Error
*** command status = Error(-1)
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

- 从 ONTAP 事件中发现 SP HBT 消息。示例：

```
cluster::> event log show
... EMERGENCY monitor.shutdown.emergency: Emergency shutdown: Environmental Reason
Shutdown (System reboot to recover the SP)
... EMERGENCY sp.ipmi.lost.shutdown: SP heartbeat stopped and cannot be recovered.
To prevent hardware damage and data loss, the system will shut down in 10 minutes.
... ALERT      callhome. sp.hbt.stopped: Call home for SP HBT STOPPED
... ERROR      asup.post.drop: AutoSupport message (HA Group Notification from
node_name (SP HBT STOPPED) ALERT) was not posted to NetApp. The system will drop the
message.
... ERROR      asup.post.drop: AutoSupport message (HA Group Notification from
node_name (SP HBT MISSED) NOTICE) was not posted to NetApp. The system will drop the
message.
```