



## cfdisk-974 : 适用于WD Cobra-F驱动器的NE12/MS12固件

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CFDISK-974>

Updated: Wed, 22 Apr 2026 07:30:34 GMT

### 问题描述

的NE12/MS12固件版本**HUT10 18**驱动器型号是一个维护版本、用于解决以下问题描述问题：  
在7到7.5年的开机时间内、驱动器上存在日志溢出问题描述、导致每隔30分钟重新启动一次。  
受影响驱动器的部件号列表：

市场营销部分	型号ID	容量	更新到
E-X4071A-R6	HUC101818CS4201	1.8 TB	NE12
E-X4069A-R ö R6	HUC101818CS4201	1.8 TB	NE12
E-X4070A-R6	HUC101818CS4204	1.8 TB	NE12
E-X4072A-R6	HUC101818CS4204	1.8 TB	NE12
E-X4122A	HUC101818CS4204	1.8 TB	NE12

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

市场营销部分	型号ID	容量	更新到
E-X4123A	HUC101818CS4204	1.8 TB	NE12
E-X4052B-R6	HUC101812CSS201	1.2 TB	MS12
E-X4054B-R6	HUC101812CSS201	1.2 TB	MS12
E-X4053B-R6	HUC101812CSS204	1.2 TB	MS12
E-X4055B-R6	HUC101812CSS204	1.2 TB	MS12
E-X4119A	HUC101812CSS204	1.2 TB	MS12
E-X4039B-R6	HUC101890CSS201	900 GB	MS12
E-X4029A-2 R6 Ω	HUC101890CSS201	900 GB	MS12
E-X4038B-R ö R6	HUC101890CSS204	900 GB	MS12
E-X4036A-R ö R6	HUC101890CSS204	900 GB	MS12
E-M ü X4091A	HUC101890CSS204	900 GB	MS12
E-X4049A-R ö R6	HUC101860CSS201	600 GB	MS12
E-X4026B-R ö R6	HUC101860CSS201	600 GB	MS12
E-X4050B-R ö R6	HUC101860CSS204	600 GB	MS12
E-X4051B-R ö R6	HUC101860CSS204	600 GB	MS12