



CHW-3133 : FAS2820 更换主板后出现不可纠正的机器检查错误

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CHW-3133>

Updated: Wed, 22 Apr 2026 08:25:45 GMT

问题描述

主板更换后系统崩溃

节点运行数小时并完成 BMC、BIOS 版本升级

PANIC: Uncorrectable Machine Check Error at CPU7. ICL_UBOX Error:

STATUS<0xba0000000000e0b> (VALID, UC, EN, MISCV, PCC, CESI (0), CERR_CNT (0), OTHER_INFO (0), MSCOD (0)

RPT(0,9,0): Mellanox CX5 Ethernet in slot 1 on Controller, Mellanox CX5 Ethernet in

slot 1 on Controller, Mellanox CX5 Ethernet in slot 1 on Controller, Mellanox CX5

Ethernet in slot 1 on Controller, RAS(20,0,2).. in process idle: cpu7 on release

9.15.1P7 (C) on Tue Apr 8 01:49:02 CEST 2025