



CHS-588 : AFF A400、FAS8300、FAS8700 : 无法使用主固件映像启动

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CHW-588>

Updated: Wed, 22 Apr 2026 07:32:35 GMT

问题描述

在AFF A400、FAS8300或FAS8700存储系统上、自动启动会因以下事件而发生abort：

```
Ready to boot.
```

```
Boot Loader version 6.4.3
```

```
Copyright (C) 2000-2003 Broadcom Corporation.
```

```
Portions Copyright (C) 2002-2019 NetApp, Inc. All Rights Reserved.
```

```
*****
```

```
*** Booted from Backup Firmware Image ***
```

```
*****
```

```
ACPI RSDP Found at 0x6c41a000
```

```
Abort AUTOBOOT
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information