



---

## CHS-519 : CHS-519—由于ADr超时、节点重新启动

<https://kb-cn-stage.netapp.com/on-prem/ontap/OHW/OHW-Issues/CHW-519>

Updated: Wed, 22 Apr 2026 07:33:11 GMT

### 问题描述

节点发生意外重新启动：

基板管理控制器(BMC)中的

CLTFLT:HA Group Notification from node-02 (CONTROLLER TAKEOVER COMPLETE AUTOMATIC)  
ALERT

日志已显示(ADR超时)：

```
Record 1127: Thu Oct 07 04:46:54.280000 2021 [IPMI.notice]: 003a | 02 | EVT:  
015201a4 | P5V | Assertion Event, "Lower Critical going low " | Reading: 0.026 |  
Threshold: 4.264
```

```
Record 1128: Thu Oct 07 04:46:55.670000 2021 [BMC.critical]: Filer Reboots
```

```
Record 1129: Thu Oct 07 04:46:55.690000 2021 [Trap Event.critical]: hwassist  
abnormal_reboot (28)
```

```
Record 1130: Thu Oct 07 04:46:55.780000 2021 [Trap Event.critical]: SNMP  
abnormal_reboot (28)
```

---

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information

Record 1131: Thu Oct 07 04:46:57.000000 2021 [SysFW.notice]: ADR Timeout  
Record 1132: Thu Oct 07 04:46:57.000000 2021 [SysFW.notice]: ADR Timeout